



Room Capacities

Room	Dimensions	Height	Sq Ft	Dinner	Cocktail
Drill Hall	153'6" x 251'4"	68'3"	38,579	1,200	1,200
1st Floor Reception Rooms					
North Corridor					
Corridor	100' x 17'	22'	1,700	88	145
Veteran's Room	45'10" x 36'3"	22'	1,663	110	150
Library	17' x 31'	22'	527	20	50
Field and Staff Room	19'3" x 40'10"	22'	920	46	74
Sub-total			4,810	264	419
South Corridor					
Corridor	100' x 17'	22'	1,700	88	145
Board of Officers Room	45'11" x 36'9"	22'	1,688	110	150
Mary Divver Room	22'11" x 36'9"	22'	842	42	74
Colonel's Room	22'4" x 35'7"	22'	685	46	74
Sub-total			4,915	286	443
North and South Corridor Rooms			9,725		
<i>Spaces for catering support, storage and coat check are included in the rental of the North and/or South Corridor (listed below).</i>					
Superintendent's Office (North Corridor)	17'0" x 28'0"	8'	476		
Outer Committee Room (North Corridor)	16'3" x 24'4"	13'	397		
Adjutant's Room (South Corridor)	33'2" x 16'5"	13'	558		
Staff Parlor (South Corridor)	16'0" x 35'0"	13'	530		
2nd Floor					
South Corridor	70'0" x 17'0"	22'	1,190	60 - 120	145
Company H	36'10" x 24'4"	18'	698	44	74
Company L ("Moose Room")	36'10" x 16'2"	18'	597	28	50